Division of Health Care Facilities

ווטופועום	of Fleatiff Care Facilitie	:5				
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01		(X3) DATE SURVEY COMPLETED	
		IDENTIFICATION NUMBER:				
)
		TN3305 B. WING			02/09/2021	
					1 02.0	0,2021
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE						
5798 HIXSON HOME PLACE						
LIFE CARE CENTER OF HIXSON						
HIXSON, TN 37343						
(X4) ID	SUMMARY STA	ATEMENT OF DEFICIENCIES	ID	PROVIDER'S PLAN OF CORRECTION	1	(X5)
PRÉFIX	EFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE		COMPLETE
TAG			TAG			DATE
				DEFICIENCY)		
N 000	000 Initial Comments		N 000			
	Construction: Type V (111)					
	Stories: 1	()				
	Plans available on site					
	Constructed: 2011					
	Sprinkled: Yes					
	Census: 59					
	Certified Beds: 108					
	A Life Safety complaint investigation of intake					
	#TN00053146 conducted by the State of Tennessee Department of Health Division of Health Licensure and Regulation Office of Health Care Facilities survey on 2/9/2021. During this					
	Life Safety complaint investigation, Life Care Center of Hixson was found in substantial compliance with the requirements of the Rules of Tennessee Department of Health Board for					
	Licensing Health Care Facilities Chapter 1200-08-06 Standards for Nursing Homes and National Fire Protection (NFPA) 101 Life Safety (2012 Edition).					
N 000 4000 0 0 N D C : :		N 000				
N 002	1200-8-6 No Deficien	cies	N 002			
	This Rule is not met	as evidenced by:				
		complaint investigation of				
	intake #TN00053146 conducted on 2/9/2021, no deficiencies were cited under 1200-08-06, Standards for Nursing Homes.					

Division of Health Care Facilities

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE